

FLOOD MONITORING CELL WATER RESOURCES DEPARTMENT **GOVT. OF BIHAR**

WEB EDITION

DAILY FLOOD INFORMATION BULLETIN 6:30 P.M									29-Aug-14
		Hydrologic	status for the I	River Basi	ins in North	Bihar			
BASIN	Today's Wat	er Level (m)	and preceding day's rainfall observed today at 6:00 AM				Nepal Rai	nfall (mm)	
NAME	District	Gauge Sites	High Flood Level	Danger Level	Water Level	Trend	Status	Gauge Site	Rainfall
	East Champaran	Chatia	70.04/02	69.15	68.00	R	Below DL	Pokhara	TRACES
	Muzaffarpur	Rewaghat	55.41/86	54.41	53.67	S	Below DL	Arughat*	NA
	Vaishali	Hajipur	50.93/48	50.32	47.88	F	Below DL	Narayanghat*	0.25
GANDAK								Bharatpur	NA
								Ghalekharkha*	0.20
								Betrawati*	64.60
								Danda*	0.00
	Breach, If any:		The damaged portion in Champaran embankment at 8 KM on left bank of Gandak river near village- Chandanpur Barwa, Block- Bagha-1, Dist-West Champaran has been restored and its strengthening work is being done at war level. The damaged portion of Sallehpur Tandaspur Chharki near Ramchandrapur village 5 km u/s of Dumariaghat bridge under Gopalganj district has been restored and its strengthening work is being carried out.						
×	East Champaran	Lalbegiaghat	67.09/75	63.20	63.23	ut. S	Above DL	Simra	0.00
BURHI GANDAK	Muzaffarpur	Sikandarpur	54.29/87	52.53	51.35	F	Below DL		
	Samastipur	Samastipur	49.38/87	46.02	45.42	S	Below DL		
	Samastipur	Rosera	46.35/87	42.63	42.34	S	Below DL		
	Khagaria	Khagaria	39.22/76	36.58	35.81	F	Below DL		
	Breach, If any:		Not Reported						
васматі	Sitamarhi	Sonakhan^	70.77	68.80	67.30	R	Below DL	Kathmandu	1.00
	Sheohar	Dubbadhar [^]	63.75	61.28	61.18	F	Below DL	Nagarkot	NA
	Sitamarhi	Kansar^	60.86	59.06	58.80	F	Below DL	Garuda*	0.00
	Muzaffarpur	Benibad	50.01/04	48.68	49.20	F	Above DL	Karmaiya*	1.20
	Darbhanga	Hayaghat	48.96/87	45.72	45.99	R	Above DL	Khokana*	0.00
B/	Darbhanga	Kamtaul	52.99/87	50.00	50.81	S	Above DL	Bhorleni*	0.00
	Darbhanga	Ekmighat	49.52/04	46.94	47.16	R	Above DL		
	Breach, if any:		Restoration work of the damaged portion in the river side slope of Bagmati left embankment near Rampur Kanth in Suppi Block under Sitamarhi district is being carried out at war level. The situation is under control.						
	Madhubani	Jainagar^	70.65	69.35	68.15	F	Below DL	Janakpur	NA
KAMLA	Madhubani	Jhanjharpur (Rail pul)^	54.34/87	50.00	50.45	F	Above DL	Sindhuli*	0.00
ΑĀ	Madhubani	Jhanjharpur	53.01/04	50.00	49.70	S	Below DL		
	Breach, If any:		The action to stop the flow of water from the damaged portion at KM 70.8 near village Kumhraul and at KM 74.0 near village Baur respectively of Kamla Balan right embankment in Ghanshyampur block under Darbhanga district is being carried out at war level.						
ıs	Supaul	Basua	48.87/04	47.75	47.66	S	Below DL	Okhaldunga	16.90
	Khagaria	Baltara	36.40/87	33.85	34.28	F	Above DL	Taplejung	11.30
	Katihar	Kursela	32.10/82	30.00	29.56	F	Below DL	Dhankuta	0.00
KOSI								Dharan	TRACES
								Jiri*	12.60
	Danash W				4 D			Mulghat*	0.00
MAHANAND,	Breach, If any:	Dham	20.00/22		t Reported	_	Delem Di	Dinata	0.00
	Purnia	Dhengraghat	38.09/68	35.65	35.61	F	Below DL	Biratnagar	0.00
	Katihar Breach, If any:	Jhawa	33.51/87						

- DL- Danger Level / R Rising / S Steady / F Falling / C Constant , NA: Not Available, /Tr: Traces / BGL: Below Gauge Level
- * Nepal rainfall taken from website of Govt. of Nepal, Ministry of Environment (hydrology.gov.np).

WRD gauge stations without raingauge.

SOURCES:

- Number of the second of t
- 3. CWC/WRD for Water Level at Gauge Sites
- 4. WWW.mfd.gov.np\Hydrology.gov.np for Nepal Rainfall
 5. For rainfall forecast issued by IMD-NA