

DAILY FLOOD INFORMATION BULLETIN 6:30 P.M									30-Aug-14	
Hydrologic status for the River Basins in North Bihar										
BASIN NAME	Today's Water Level (m) and preceding day's rainfall observed today at 6:00 AM							Nepal Rainfall (mm)		
	District	Gauge Sites	High Flood Level	Danger Level	Water Level	Trend	Status	Gauge Site	Rainfall	
GANDAK	East Champaran	Chatia	70.04/02	69.15	68.07	F	Below DL	Pokhara	4.20	
	Muzaffarpur	Rewaghat	55.41/86	54.41	53.69	S	Below DL	Arughat*	NA	
	Vaishali	Hajipur	50.93/48	50.32	47.80	S	Below DL	Narayanghat*	4.83	
								Bharatpur	NA	
								Ghalekharkha*	0.60	
								Betrawati*	5.60	
								Danda*	0.00	
	Breach, If any:		The damaged portion in Champaran embankment at 8 KM on left bank of Gandak river near village- Chandanpur Barwa, Block- Bagha-1, Dist-West Champaran has been restored and its strengthening work is being done at war level. The damaged portion of Sallehpur Tandaspur Chiharki near Ramchandrapur village 5 km u/s of Dumariaghat bridge under Gopalganj district has been restored and its strengthening work is being carried out.							
BURHI GANDAK	East Champaran	Lalbegiaghat	67.09/75	63.20	63.10	F	Below DL	Simra	9.00	
	Muzaffarpur	Sikandarpur	54.29/87	52.53	51.36	R	Below DL			
	Samastipur	Samastipur	49.38/87	46.02	45.37	S	Below DL			
	Samastipur	Rosera	46.35/87	42.63	42.33	S	Below DL			
	Khagaria	Khagaria	39.22/76	36.58	35.72	F	Below DL			
		Breach, If any:		Not Reported						
BAGMATI	Sitamarhi	Sonakhan^	70.77	68.80	67.05	R	Below DL	Kathmandu	6.00	
	Sheohar	Dubbadhar^	63.75	61.28	60.80	F	Below DL	Nagarkot	NA	
	Sitamarhi	Kansar^	60.86	59.06	58.25	F	Below DL	Garuda*	0.20	
	Muzaffarpur	Benibad	50.01/04	48.68	49.19	S	Above DL	Karmaiya*	0.00	
	Darbhangha	Hayaghat	48.96/87	45.72	46.10	R	Above DL	Khokana*	0.00	
	Darbhangha	Kamtaul	52.99/87	50.00	50.93	R	Above DL	Bhorleni*	2.20	
	Darbhangha	Ekmgihat	49.52/04	46.94	47.19	S	Above DL			
		Breach, If any:		Restoration work of the damaged portion in the river side slope of Bagmati left embankment near Rampur Kanth in Suppi Block under Sitamarhi district is being carried out at war level. The situation is under control.						
KAMLA	Madhubani	Jainagar^	70.65	69.35	68.85	R	Below DL	Janakpur	NA	
	Madhubani	Jhanjharpur (Rail pul)^	54.34/87	50.00	50.20	F	Above DL	Sindhuli*	0.00	
	Madhubani	Jhanjharpur	53.01/04	50.00	49.65	F	Below DL			
		Breach, If any:		The action to stop the flow of water from the damaged portion at KM 70.8 near village Kumhraul and at KM 74.0 near village Baur respectively of Kamla Balan right embankment in Ghanshyampur block under Darbhanga district is being carried out at war level. The flow of water in the countryside has been stopped restoring the breach point at KM 70.8.						
KOSI	Supaul	Basua	48.87/04	47.75	47.69	F	Below DL	Okhaldunga	TRACES	
	Khagaria	Baltara	36.40/87	33.85	34.23	R	Above DL	Taplejung	0.30	
	Katihar	Kursela	32.10/82	30.00	29.43	F	Below DL	Dhankuta	0.00	
								Dharan	NA	
								Jiri*	0.60	
								Mulghat*	0.00	
	Breach, If any:		Not Reported							
MAHANANDI	Purnia	Dhengraghat	38.09/68	35.65	35.14	F	Below DL	Biratnagar	3.00	
	Katihar	Jhawa	33.51/87	31.40	30.80	F	Below DL			
		Breach, If any:		Not Reported						

DL- Danger Level / R - Rising / S - Steady / F - Falling / C - Constant , NA : Not Available, /Tr: Traces / BGL: Below Gauge Level
 * Nepal rainfall taken from website of Govt. of Nepal, Ministry of Environment (hydrology.gov.np).
 ^ WRD gauge stations without raingauge.

SOURCES :

- Warning level for rainfall source: Hydrology.gov.np
- Rainfall forecast Based on IMD Forecast on : 30-Aug-14
- CWC/WRD for Water Level at Gauge Sites
- WWW.mfd.gov.np/Hydrology.gov.np for Nepal Rainfall
- For rainfall forecast issued by IMD-NA

Compiled at FMISC, Anisabad, Patna - 2