

**GANDAK BARRAGE GATE REPORT**

DATE	TIME	EAST MAIN CANAL HR-1 GATE LEVEL (ft.)	EAST MAIN CANAL HR-2 GATE LEVEL (ft.)	EAST MAIN CANAL HR-3 GATE LEVEL (ft.)	EAST MAIN CANAL HR-4 GATE LEVEL (ft.)	EAST MAIN CANAL HR-5 GATE LEVEL (ft.)	EAST MAIN CANAL HR-6 GATE LEVEL (ft.)	EAST MAIN CANAL HR-7 GATE LEVEL (ft.)	EAST MAIN CANAL HR-8 GATE LEVEL (ft.)
27-Jun-19	6:00:00 AM	2	4	4	5	5	4.3	4	2
27-Jun-19	7:00:00 AM	0	0	0	0	0	0	0	0
27-Jun-19	8:00:00 AM	0	0	0	0	0	0	0	0
27-Jun-19	9:00:00 AM	0	0	1	1	0.2	0	0	0
27-Jun-19	10:00:00 AM	1	2	3	3	3	3	2	0.5
DATE	TIME	WEST MAIN CANAL HR-1 GATE LEVEL (ft.)	WEST MAIN CANAL HR-2 GATE LEVEL (ft.)	WEST MAIN CANAL HR-3 GATE LEVEL (ft.)	WEST MAIN CANAL HR-4 GATE LEVEL (ft.)	WEST MAIN CANAL HR-5 GATE LEVEL (ft.)	WEST MAIN CANAL HR-6 GATE LEVEL (ft.)	WEST MAIN CANAL HR-7 GATE LEVEL (ft.)	WEST MAIN CANAL HR-8 GATE LEVEL (ft.)
27-Jun-19	6:00:00 AM	3	5	5	5	5	5	4	2.5
27-Jun-19	7:00:00 AM	3	5	5	5	5	5	4	2.5
27-Jun-19	8:00:00 AM	3	5	5	5	5	5	4	2.5
27-Jun-19	9:00:00 AM	3	5	5	5	5	5	4	2.5
27-Jun-19	10:00:00 AM	3	5	5.3	6	6	6	5	3
DATE	TIME	LEFT UNDER SLUICE-1 GATE LEVEL(ft.)	LEFT UNDER SLUICE-2 GATE LEVEL(ft.)	LEFT UNDER SLUICE-3 GATE LEVEL(ft.)	LEFT UNDER SLUICE-4 GATE LEVEL(ft.)	LEFT UNDER SLUICE-5 GATE LEVEL(ft.)	LEFT UNDER SLUICE-6 GATE LEVEL(ft.)		
27-Jun-19	6:00:00 AM	2	2	0.1	0.1	0.2	0.2		
27-Jun-19	7:00:00 AM	3	5	0.1	0.1	0.2	0.2		
27-Jun-19	8:00:00 AM	3	5	0.1	0.1	0.2	0.2		
27-Jun-19	9:00:00 AM	3	5	0.1	0.1	0.2	0.2		
27-Jun-19	10:00:00 AM	1.5	1.5	0.1	0.1	0.2	0.2		
DATE	TIME	SPILLWAY-7 GATE LEVEL(ft.)	SPILLWAY-8 GATE LEVEL(ft.)	SPILLWAY-9 GATE LEVEL(ft.)	SPILLWAY-10 GATE LEVEL(ft.)	SPILLWAY-11 GATE LEVEL(ft.)	SPILLWAY-12 GATE LEVEL(ft.)		
27-Jun-19	6:00:00 AM	0.2	0.4	0.3	0.3	0.1	0.4		
27-Jun-19	7:00:00 AM	0.2	0.4	0.3	0.3	0.1	0.4		
27-Jun-19	8:00:00 AM	0.2	0.4	0.3	0.3	0.1	0.4		
27-Jun-19	9:00:00 AM	0.2	0.4	0.3	0.3	0.1	0.4		
27-Jun-19	10:00:00 AM	0.2	0.4	0.3	0.3	0.1	0.4		

DATE	TIME	SPILLWAY-13 GATE LEVEL(ft.)	SPILLWAY-14 GATE LEVEL(ft.)	SPILLWAY-15 GATE LEVEL(ft.)	SPILLWAY-16 GATE LEVEL(ft.)	SPILLWAY-17 GATE LEVEL(ft.)	SPILLWAY-18 GATE LEVEL(ft.)
27-Jun-19	6:00:00 AM	0.4	0.2	0.1	0.2	0.1	0.2
27-Jun-19	7:00:00 AM	0.4	0.2	0.1	0.2	0.1	0.2
27-Jun-19	8:00:00 AM	0.4	0.2	0.1	0.2	0.1	0.2
27-Jun-19	9:00:00 AM	0.4	0.2	0.1	0.2	0.1	0.2
27-Jun-19	10:00:00 AM	0.4	0.2	0.1	0.2	0.1	0.2
DATE	TIME	SPILLWAY-19 GATE LEVEL(ft.)	SPILLWAY-20 GATE LEVEL(ft.)	SPILLWAY-21 GATE LEVEL(ft.)	SPILLWAY-22 GATE LEVEL(ft.)	SPILLWAY-23 GATE LEVEL(ft.)	SPILLWAY-24 GATE LEVEL(ft.)
27-Jun-19	6:00:00 AM	0.1	0.2	0.4	0.1	0.2	0.1
27-Jun-19	7:00:00 AM	0.1	0.2	0.4	0.1	0.2	0.1
27-Jun-19	8:00:00 AM	0.1	0.2	0.4	0.1	0.2	0.1
27-Jun-19	9:00:00 AM	0.1	0.2	0.4	0.1	0.2	0.1
27-Jun-19	10:00:00 AM	0.1	0.2	0.4	0.1	0.2	0.1
DATE	TIME	RIVER SLUICE RS-25 GATE LEVEL(ft.)	RIVER SLUICE RS 26 GATE LEVEL(ft.)	RIVER SLUICE RS-27 GATE LEVEL(ft.)	RIVER SLUICE RS-28 GATE LEVEL(ft.)	RIVER SLUICE RS-29 GATE LEVEL(ft.)	RIVER SLUICE RS-30 GATE LEVEL(ft.)
27-Jun-19	6:00:00 AM	2	2	1	1	1	1
27-Jun-19	7:00:00 AM	2	2	3	2	2.1	2.1
27-Jun-19	8:00:00 AM	2	2	3	2	2.1	2.1
27-Jun-19	9:00:00 AM	2	2	3	2	2.1	2.1
27-Jun-19	10:00:00 AM	0.5	0.5	1.4	0.5	1	1
DATE	TIME	RIGHT UNDER SLUICE-31 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-32 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-33 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-34 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-35 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-36 GATE LEVEL(ft.)
27-Jun-19	6:00:00 AM	0.2	0.2	0.1	0.2	1	1
27-Jun-19	7:00:00 AM	0.2	0.2	0.1	0.2	1	1
27-Jun-19	8:00:00 AM	0.2	0.2	0.1	0.2	1	1
27-Jun-19	9:00:00 AM	0.2	0.2	0.1	0.2	1	1
27-Jun-19	10:00:00 AM	0.2	0.2	0.1	0.2	1	1

**GANDAK BARRAGE DISCHARGE REPORT**

<b>DATE</b>	<b>TIME</b>	<b>UP STREAM WATER LEVEL (ft.)</b>	<b>DOWN STREAM WATER LEVEL (ft.)</b>	<b>EAST MAIN CANAL</b>	<b>WEST MAIN CANAL</b>	<b>DOWN STREAM</b>	<b>TOTAL DISCHARGE (Cusec.)</b>
27-Jun-19	6:00:00 AM	362	344.1	6000	12000	10450	28450
27-Jun-19	7:00:00 AM	362	345	0	12000	14800	26800
27-Jun-19	8:00:00 AM	362	345.7	0	12000	19750	31750
27-Jun-19	9:00:00 AM	362	345.7	1000	12000	19750	32750
27-Jun-19	10:00:00 AM	362	345.4	6000	12000	17500	35500