

**GANDAK BARRAGE GATE REPORT**

DATE	TIME	EAST MAIN CANAL HR-1 GATE LEVEL (ft.)	EAST MAIN CANAL HR-2 GATE LEVEL (ft.)	EAST MAIN CANAL HR-3 GATE LEVEL (ft.)	EAST MAIN CANAL HR-4 GATE LEVEL (ft.)	EAST MAIN CANAL HR-5 GATE LEVEL (ft.)	EAST MAIN CANAL HR-6 GATE LEVEL (ft.)	EAST MAIN CANAL HR-7 GATE LEVEL (ft.)	EAST MAIN CANAL HR-8 GATE LEVEL (ft.)
30-Oct-19	11:00:00 AM	0	0	0	0	0	0	0	0
30-Oct-19	12:00:00 PM	0	0	0	0	0	0	0	0
30-Oct-19	1:00:00 PM	0	0	0	0	0	0	0	0
30-Oct-19	2:00:00 PM	0	0	0	0	0	0	0	0
30-Oct-19	3:00:00 PM	0	0	0	0	0	0	0	0
DATE	TIME	WEST MAIN CANAL HR-1 GATE LEVEL (ft.)	WEST MAIN CANAL HR-2 GATE LEVEL (ft.)	WEST MAIN CANAL HR-3 GATE LEVEL (ft.)	WEST MAIN CANAL HR-4 GATE LEVEL (ft.)	WEST MAIN CANAL HR-5 GATE LEVEL (ft.)	WEST MAIN CANAL HR-6 GATE LEVEL (ft.)	WEST MAIN CANAL HR-7 GATE LEVEL (ft.)	WEST MAIN CANAL HR-8 GATE LEVEL (ft.)
30-Oct-19	11:00:00 AM	0	0	0	0	0	0	0	0
30-Oct-19	12:00:00 PM	0	0	0	0	0	0	0	0
30-Oct-19	1:00:00 PM	0	0	0	0	0	0	0	0
30-Oct-19	2:00:00 PM	0	0	0	0	0	0	0	0
30-Oct-19	3:00:00 PM	0	0	0	0	0	0	0	0
DATE	TIME	LEFT UNDER SLUICE-1 GATE LEVEL(ft.)	LEFT UNDER SLUICE-2 GATE LEVEL(ft.)	LEFT UNDER SLUICE-3 GATE LEVEL(ft.)	LEFT UNDER SLUICE-4 GATE LEVEL(ft.)	LEFT UNDER SLUICE-5 GATE LEVEL(ft.)	LEFT UNDER SLUICE-6 GATE LEVEL(ft.)		
30-Oct-19	11:00:00 AM	0.8	0.9	0.4	1.3	1.4	5		
30-Oct-19	12:00:00 PM	0.4	0.3	0.3	0.4	1	9.9		
30-Oct-19	1:00:00 PM	0.4	0.3	0.4	0.4	4.9	9.9		
30-Oct-19	2:00:00 PM	0.4	0.3	0.4	0.4	3.1	9.9		
30-Oct-19	3:00:00 PM	0.4	0.3	0.4	0.4	3.2	9.9		
DATE	TIME	SPILLWAY-7 GATE LEVEL(ft.)	SPILLWAY-8 GATE LEVEL(ft.)	SPILLWAY-9 GATE LEVEL(ft.)	SPILLWAY-10 GATE LEVEL(ft.)	SPILLWAY-11 GATE LEVEL(ft.)	SPILLWAY-12 GATE LEVEL(ft.)		
30-Oct-19	11:00:00 AM	0.3	0.5	0.7	0.4	0	0		
30-Oct-19	12:00:00 PM	0.3	0.6	0.7	0.5	0	0		
30-Oct-19	1:00:00 PM	0.4	0.6	0.7	0.5	0	0		
30-Oct-19	2:00:00 PM	0	0.2	0	0	0	0		
30-Oct-19	3:00:00 PM	0	0.2	0	0	0	0		

DATE	TIME	SPILLWAY-13 GATE LEVEL(ft.)	SPILLWAY-14 GATE LEVEL(ft.)	SPILLWAY-15 GATE LEVEL(ft.)	SPILLWAY-16 GATE LEVEL(ft.)	SPILLWAY-17 GATE LEVEL(ft.)	SPILLWAY-18 GATE LEVEL(ft.)
30-Oct-19	11:00:00 AM	0	0	0	0.2	0	0
30-Oct-19	12:00:00 PM	0	0	0	0.2	0	0
30-Oct-19	1:00:00 PM	0	0	0	0.2	0	0
30-Oct-19	2:00:00 PM	0	0	0	0.3	0	0
30-Oct-19	3:00:00 PM	0	0	0	0.2	0	0
DATE	TIME	SPILLWAY-19 GATE LEVEL(ft.)	SPILLWAY-20 GATE LEVEL(ft.)	SPILLWAY-21 GATE LEVEL(ft.)	SPILLWAY-22 GATE LEVEL(ft.)	SPILLWAY-23 GATE LEVEL(ft.)	SPILLWAY-24 GATE LEVEL(ft.)
30-Oct-19	11:00:00 AM	0	0	6.9	7	7	5.2
30-Oct-19	12:00:00 PM	0	0	8.9	9	9	7
30-Oct-19	1:00:00 PM	0	0	8.9	9.1	9	7
30-Oct-19	2:00:00 PM	0	0	8.9	9.1	9	7
30-Oct-19	3:00:00 PM	0	0	8.9	9	9	7
DATE	TIME	RIVER SLUICE RS-25 GATE LEVEL(ft.)	RIVER SLUICE RS 26 GATE LEVEL(ft.)	RIVER SLUICE RS-27 GATE LEVEL(ft.)	RIVER SLUICE RS-28 GATE LEVEL(ft.)	RIVER SLUICE RS-29 GATE LEVEL(ft.)	RIVER SLUICE RS-30 GATE LEVEL(ft.)
30-Oct-19	11:00:00 AM	2.2	0.6	0.5	0.5	0.6	0.6
30-Oct-19	12:00:00 PM	2.2	0.6	0.5	0.5	0.8	0.6
30-Oct-19	1:00:00 PM	5	5.1	1.9	0.6	0.8	0.6
30-Oct-19	2:00:00 PM	5	5.1	1.9	0.6	0.8	0.6
30-Oct-19	3:00:00 PM	5	5.1	1.9	0.6	0.8	0.6
DATE	TIME	RIGHT UNDER SLUICE-31 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-32 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-33 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-34 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-35 GATE LEVEL(ft.)	RIGHT UNDER SLUICE-36 GATE LEVEL(ft.)
30-Oct-19	11:00:00 AM	0.5	0.4	0.4	0.6	0.9	0.8
30-Oct-19	12:00:00 PM	0.5	0.4	0.4	0.6	0.9	0.8
30-Oct-19	1:00:00 PM	0.5	0.4	0.5	0.6	0.9	0.8
30-Oct-19	2:00:00 PM	0.6	0.4	0.5	0.6	0.9	0.8
30-Oct-19	3:00:00 PM	0.6	0.4	0.4	0.6	0.9	0.8

**GANDAK BARRAGE DISCHARGE REPORT**

<b>DATE</b>	<b>TIME</b>	<b>UP STREAM WATER LEVEL (ft.)</b>	<b>DOWN STREAM WATER LEVEL (ft.)</b>	<b>EAST MAIN CANAL</b>	<b>WEST MAIN CANAL</b>	<b>DOWN STREAM</b>	<b>TOTAL DISCHARGE (Cusec.)</b>
30-Oct-19	11:00:00 AM	360	346	0	0	22000	22000
30-Oct-19	12:00:00 PM	360	345.8	0	0	20500	20500
30-Oct-19	1:00:00 PM	360	345.4	0	0	17500	17500
30-Oct-19	2:00:00 PM	360	344.8	0	0	13800	13800
30-Oct-19	3:00:00 PM	360	344.5	0	0	12250	12250